



THE TINTING COMPANY

FAST & FLUID MANAGEMENT B.V.
P.O. Box 220 | 2170 AE Sassenheim
Hub van Doorneweg 31 | 2171 KZ Sassenheim
Telephone +31(0)252 240 842 | Fax +31(0)252 240 882 |
www.fast-fluid.com

Recommended Spare Partlist

HA450 (Refill + High Speed)

Quantity	Partnr.	Description	Page	Item
1	1602782-SP	Fuse10AT (10pcs)	6932-A	
1	1861979-SP	sensor5,thomesen.assy,HA/TM From 25-07-05	6920	
1	1863284-SP	Sensor 6,tablepos.TMXL From 25-07-05	6920	
1	1864020-SP	sensor2,4,HA450	6921	
1	1861975-SP	Proximity switch cansensor 18mm	6930	
1	1812528-sp	Switch Safety	6920	
1	1863891-SP	Powersupply 48V 300W	6922	
1	1864860-sp	Powerboard 2002 new	6920	
1	1813952-SP	Container,brush,assy,HA450 up to sn 931570	6935-A	
1	1864888-SP	Container,brush,assy,HA450 POM as of sn 931571	6935-B	
1	1814029-SP	Brush only HA450	6935-A/B/C	
1	1863862-SP	Brush,motor,micro,screws,3pcs up to sn 931570	6935-A	
1	1864889-SP	Brush, motor, w coupling as of sn 931571	6935-B/C	
4	1862422-SP	Wheel, transferring, centric, 35mm	6935-C	
1	1362230-SP	O-ring,can,vit,15,88x2,62 10st	6941	
1	1861350-SP	O-ring,vit,23,52 x 1,78 10pcs (2oz)	6961	
1	1863714-SP	O-ring,vit,38 x 2 10pcs (5oz)	6963	
1	1863653-SP	O-ring,vit,52 x 2 10pcs (10oz)	6964	
1	1810936-SP	piston solid teflon, 2oz, 4-seals HA (set for 1 pump)	6962	
1	1810933-SP	piston solid teflon, 5oz, 4-seals HA (set for 10 pumps)	6963	
1	1813322-SP	piston solid teflon, 10oz, 4-seals HA (set for 10 pumps)	6964	
1	1817841-sp	Ring, click tube, ballvalve (5 pcs)	6964	
1	1863708-SP	Motor 404 938 Agitation	6932-A	
1	1863527-SP	Ballvalve 2005,Disk 5pcs+Tool	6961	
1	1861940-SP	Motor 80,805,0,24V,i=49 (HA200/400 TT)	6933	
1	1861943-SP	Motor, valve, 80.805.0,24V,i=245	6921	
1	1862015-SP	Actuater,cantable,with screw8x	6911	
1	1863480-SP	Repair kit,cable defect cantable.		

HA450 REFILL				
1	1814983-SP	Refill valve	6936-A/B/C	
1	1815200-SP	Floater	6936-A/B/C	
1	1864071-SP	Sensor Floater	6936-A/B/C	

HA450 Speedset				
1	1814849-SP	TT motor HA450	6980	
1	1864594-sp	Piston Detector complete	6934	
1	1815318-SP	Micro switch piston detector up to sn 871237	6975-A	